


With Pool Drainage, numerous points of cracking witnessed, but one notable is at the transition to the deeper end of the pool is the bottom decking showing a 'spreading' motion of cracking






Other areas show newer signs of movement and degradation. Sharper edges at cracking

Evidence of separation/settlement. Due to the slope of the pool deck, prolonged infiltration of water under the deck.

Certain areas show aged debris build up and rounded edges at the cracking

Previous Patching failure. Exposure to chlorinated water, and movement weakens patching and allowing water migration into the deck and compromise reinforcing steel





Patching Material bond held to deck, movement presenting after patch was made


Continuous signs of movement in the decking at varying rates



Continuous signs of movement in the decking at varying rates



Continuous signs of movement in the decking at varying rates



Continuous signs of movement in the decking at varying rates



Apparent growth in cracking on deck.

Aerial was taken 8/1/2025.
In person was taken 4/29/2026