


A-Core Detection Report

Scan File: RS_335140003_002331
Scan Name: -
Date / Time: 2026-04-16 08:42:54
Comment: -




x: 9.8 in y: 9.8 in z: 1.0 in Thickness: 1.0 in
Overlay: - in Concrete: 9.0 Method: Advanced Cut-off: - in

Project name: NM Tech Pool Customer: Franken
Location: Scan 1 Object: -
User: -
Comment: -

A-Core Detection Report

Scan File: RS_335140003_002332
Scan Name: -
Date / Time: 2026-04-16 08:45:25
Comment: -




x: 9.8 in y: 9.8 in z: 1.7 in Thickness: 1.2 in
Overlay: - in Concrete: 9.0 Method: Advanced Cut-off: - in

Project name: NM Tech Pool Customer: Franken
Location: Scan 2 Object: -
User: -
Comment: -

A-Core Detection Report

Scan File: RS_335140003_002334
 Scan Name: -
 Date / Time: 2026-04-16 08:57:19
 Comment: -




x: 9.8 in y: 9.8 in z: 0.7 in Thickness: 1.6 in
 Overlay: - in Concrete: 9.0 Method: Advanced Cut-off: - in

Project name: NM Tech Pool Customer: Franken
 Location: Scan 4 Object: -
 User: -
 Comment: -

Drillholes:	x:	y:	Depth:	Diameter:	Comment:
1.	9.8 in	9.8 in	11.8 in	1.6 in	-

A-Core Detection Report

Scan File: RS_335140003_002335
Scan Name: -
Date / Time: 2026-04-16 09:00:09
Comment: -




x: 9.8 in y: 9.8 in z: 2.2 in Thickness: 2.4 in
Overlay: - in Concrete: 9.0 Method: Advanced Cut-off: - in

Project name: NM Tech Pool Customer: Franken
Location: Scan 5 Object: -
User: -
Comment: -

A-Core Detection Report

Scan File: RS_335140003_002336
Scan Name: -
Date / Time: 2026-04-16 09:02:10
Comment: -



x: 9.8 in y: 9.8 in z: -0.2 in Thickness: 2.4 in
Overlay: - in Concrete: 9.0 Method: Advanced Cut-off: - in

Project name: NM Tech Pool Customer: Franken
Location: Scan 6 Object: -
User: -
Comment: -