Chevron Mining Inc. Questa Tailing Boundary	and a state of the second seco	Chevron Mining Inc. Questa Mine and Mill Boundary
Directions To Questa Mine Tailing Facility:	Directions To Questa Mine Goathill Facility:	Directions To Questa Mine Goathill Facility:
 On State Road 522, head north to Questa and turn left on Abra Rd (right if heading south). Proceed .39 miles west and turn left onto the Tailing access road. 	 On State Road 522, head north to Questa and turn right on State Road 38 (left if heading south). Proceed 3.5 miles east and turn left onto the Goathill access road and following signs to Guard Shack. 	(left if heading south).
Drawing / Reference Title Disaving / Reference Title Revision # Data SI 200		avn By Richard Vialpando werd By Nitials Date Date Date Date Date Date Date Date

